
1720 Woodfield Dr Playground Safety Inspection 2019



Completed By: Justin Moos, CPSI 5/3/2019





- Decks cracking Recommend replacement. Cracking will continue to expand. Steel unprotected. Monitor closely
 - 1. Priority 3.






Double Slide

- Rail cap missing. Clothing, hands and other loose items could get caught. Entanglement hazard. Replacement needed immediately.
 - 1. Priority 1





- Lower Deck Clamps missing. Aftermarket fastner used. Not recommended. Replace with OEM components only
 - 1. Priority 3








- 1. Carriage bolt head Must be flush. Entanglement hazard
 - 1. Priority 1
- 2. Pop rivet not flush, Top deck. High on post. Replace with Aluminum
 - 1. Priority 3

1



2




- Clamps tightened unevenly. Recommend retighten of all clamps
 - 1. Priority 4



1





Summary

- 1. Decks are showing signs of wear and cracking Replacement parts are needed.
- 2. Slide Cap must be resolved immediately.
- 3. Aftermarket hardware fix is not recommended. OEM parts needed.
- Swings overall are in good condition.
 Recommend new swing seats and chains with improved design. Parts can be provided for this.
- Loose hardware needs to be tightened and flush.
 Recommend tightening all fasteners and clamp hardware.

Safety Ratings

- Priority 1 Safety Concern: Most Serious Violation. Non-Compliant Safety concern that may result in permanent disability, loss of life or body part. Conditions should be corrected immediately.
- Priority 2 Safety Concern: Non-Compliant Safety Concern that may result in temporary disability. Condition should be corrected as soon as possible.
- Priority 3 Safety Concern: Non-Compliant Safety Concern that is likely to cause a minor (nondisabling) injury. Condition should be corrected as soon as possible or if condition worsens.
- Priority 4 Safety Concern: Non-Compliant Safety Concern whose potential to cause injury is very minimal. Condition should be corrected as soon as possible or if condition worsens.
- No Violation: Also known as Priority 5. The item has been determined to be compliant with CPSC and ASTM guidelines. Continued ongoing preventative maintenance is recommended.